

Citroen 2CV6 4 Door Saloon 1983: Model: Charleston 602 cc

Phase 3.

Boot lid prepared for painting.



Under seal on going.



Some tricky areas to reach

Making sure all axel stands and jack in place.



This is the worst part, getting to all the important places as you do not wish

go there again for a long time. Materials used. 75% Underseal, 25% Old engine oil.

New blanket now fitted



Boot interior finished.

Scuttle in poor condition



Bumpers being restored.



Ready to fit front wings



front bumper and wings finished.



Re-lining the door panels (Free hand)



Re furnishing the scuttle



One of the most trying things has been cleaning all the rust off the underside and re-sealing, despite the help of tripods and jacks we could not get to areas at the centre and around the chassis. However a member of the Y.T.C. came to my aid and offered me his hydraulic lift at his home which we completed in know time. So a big thanks to a member of the Y.T.C. Michael Broadbent for his help.